


# Welding Filters

## MAIN PROBLEM:

Single workplace for welding of small parts.  
Extraction and filtration of welding fumes is necessary.

## SOLUTION:

Extraction arm BEA fixed to hanging self-cleaning filter.



## EQUIPMENT USED FOR SOLUTION:

Equipm.	Pos. on pic.	Description	Pcs
	2	Extraction arm <b>BEA-M-2HL</b> with lamp in the hood. Two buttons on top of the hood (lamp switching on/off, fan switching on/off). Length – 2m. Direct mounting on the filter.	1
	1	Mechanical filter <b>DCSC-W-1-00-P12</b> with self-cleaning system, mounted on the wall, connected to the compressor 3 and equipped with the fan in noise reduction jacket 4.	1
	5	Control unit, allowing connection of up to 4 extraction arms with integrated lighting.	1