
# Welding Extraction arms

## **MAIN PROBLEM:**

Two welding workplaces close to each other and to the wall. No filtration needed. Large parts may be welded.

#### **SOLUTION:**

Two extraction arms with consoles connected to extraction fan.



## **EQUIPMENT USED FOR SOLUTION:**

Equipm.	Pos. on pic.	Description	Pcs
	1	Extraction arm with console <b>EF-M-4530-L</b> . Working radius – 7 m.  Lighting installed into the hood and operated by the switch in the hood via control unit ③. Fan can be switched on/off by the second switch in the hood.	2
To large	2	Extraction fan <b>VMK-4700</b> allowing connection of two extraction arms via T-joint 4. Productivity: 1000-4000 m <sup>3</sup> /h. Pressure: 1200-2380 Pa. Used with a silencer 6 and a connection piece 6.	1

